

RECEIVED  
CENTRAL FAX CENTER

DEC 12 2006

Remarks (explanation)

We found error in Fig. 6 of this application. Two different devices were numbered as 454 and two different devices were numbered 452. We submit the corrected figure and corresponding part of the specification:

Digital signal processor renumbered as 453; A/D converter renumbered as 455.


**CONCLUSION**

It is submitted that the present application is in form for allowance, and such action is respectfully requested.

Respectfully submitted,


Celight, Inc.

Date: 12/8/2006

By: 

Isaac Shpanzer

Date: 12/8/2006

By: 

Arkady Kaplan

Date: 12/8/2006

By: 

Aviv Salomon

Date: 12/8/2006

By: 

Yaakov Achiam

Date: 12/8/2006

By: 


Jacob Khurgin

Date: 12/8/2006

By: 


Michael Tseytin

Date: 12/8/2006

By: 


Pak Shing Cho

Date: 12/8/2006

By: 

Arthur Greenblatt

Date: 12/8/2006

By: 

Christopher Kerr

Date: 12/8/2006

By: 

Geoffrey Harston

12200 Tech Rd. Suite 300  
Silver Spring MD 20904  
Tel: 301-625-7000  
Fax: 301-625-7001